

REMARKS

Figures 2c and 2d have been amended as per the attached 2 sheets entitled "Replacement Sheet". Applicant has further submitted 2 sheets entitled "Annotated Marked-Up Drawings" showing the amendments. No new matter has been added by these amendments, which are meant to correct technical oversights.

In particular the drawings have been amended as follows:

1. Fig. 2c - The box depicting high power midspan power insertion equipment 360 has been resized to properly comprise third and fourth transformers 50 and midpan PSE 310.
2. Fig. 2c – Excess connections within high power midspan power insertion equipment 360 have been eliminated.
3. Fig. 2c – Fifth transformer 50 has been shifted left to properly show the connection with an end of fifth twisted pair connection 60, and the center tap connection to power combiner 220. The label for the data pair connection at the secondary of fifth transformer 50 has been shifted to the right as shown at the secondary of sixth transformer 50.
4. Fig. 2d - The box depicting power midspan power insertion equipment 160 has been resized to properly comprise third and fourth transformers 50 and midpan PSE 40.
5. Fig. 2d – Excess connections within midspan power insertion equipment 160 have been eliminated.
6. Fig. 2d – Fifth transformer 50 has been shifted left to properly show the connection with an end of fifth twisted pair connection 60, and the center tap connection to power combiner 220. The label for the data pair

connection at the secondary of fifth transformer 50 has been shifted to the right as shown at the secondary of sixth transformer 50.

Support for these amendments can be found in the originally filed specification and in particular at paragraphs 62 – 65 for Fig. 2c and paragraphs 68 – 70 for Fig. 2d.

CONCLUSION

In view of the foregoing, entering of the amendment is herein solicited. The Examiner is encouraged to contact Applicant's undersigned agent by telephone if it would in any way aid in the advancement of this application to issue.

Respectfully submitted,

Dated: July 25, 2004



Simon Mark Kahn - Reg. No. 48,249
Intellectual Property Manager
PowerDsine, Ltd.

Tel: 1-703-486-1150
Fax: 1-703-892-4510